

Fiber Optic Instrument Adapters – SOC and UCI

CONNECTOR TYPE DESCRIPTION	SOC ADAPTER		UPI-PC ADAPTER	
	CAT. NO.	UPC NO.	CAT. NO.	UPC NO.
MIL-T-29504/4 & /5 Termini	 T1038	60589	Use hybrid cable * or FoPro® ^x	
Mini-BNC	 T1047	60591	Use hybrid cable only *	
MT-RJ †	 T13A2	60605 †	Use hybrid cable only *	
MT-RJ Ferrule Only †	 T13AF	60606 †	Use hybrid cable only *	
MU	 T10MU	60601	Use hybrid cable * or FoPro® ^x	
SC	 1062	60575	 ASC-108	60574
SMA 905/906	 T1087	60596	 ASM-90	60702
ST	 T1030	60577	 ATS-108	60573
STRATOS 430/ HOLTEK 38000	 T1057	60593	Use hybrid cable only *	
TOSLINK – Simplex	 T10TB	60602	Use hybrid cable only *	
TOSLINK – Duplex (Set of 2)	 T10TD	60603	Use hybrid cable only *	
Versatile Link – V/Z PIN	 T10ZP	60604	Use hybrid cable only *	
VFO – Radiall	 T1081	60594	Use hybrid cable only *	

* FoPro ferrule options include 2.5 mm, 1.57 mm (MIL-style 16AWG optical contacts) and 1.25 mm.

* When using a Hybrid Adapter Cable, the instrument UCI adapter and one end of the Hybrid Adapter Cable should be a commonly available connector type. (i.e. FC, SC or ST)

† SOC adapter for use only with the 556MT Optical Power Meter on page 298.



90SOC (60687)
SOC adapter tool for easy installation and removal of SOC adapters from instrument interfaces.

Voice • Data • Video

USA Tel: 800.435.0786
Fax: 800.451.2632

Canada Tel: 800.435.0786
Fax: 800.524.2853

International Tel: +1.815.397.7070
Fax: +1.815.397.9247