

Electrofusion Fittings: Transition Saddles (Corp Saddles)

Outlet Material: Brass 360 Alloy

Compression Ring Material: Stainless 304



(PE3408/PE4710) ELECTROFUSION TRANSITION SADDLE w/Brass Outlet & CC Threads

Outlet Size	Main Size	Outlet Type	Pin Type	Clamp Type	Part Number	Pack. Qty.	Wt.	AWWA
2" CC	2" IPS	Brass	4.7 R	B	call	-	-	-
2" CC	3" IPS	Brass	4.7 R	C	call	-	-	-
2" CC	4" IPS/DIPS	Brass	4.7 R	D/L	10004705	5	3.65	YES
2" CC	6" IPS/DIPS	Brass	4.7 R	E/M	10004746	5	3.80	YES
2" CC	8" IPS	Brass	4.7 R	H	10007751	5	3.60	YES
2" CC	8" DIPS	Brass	4.7 S	H	10004729	5	3.85	YES
2" CC	10" IPS	Brass	4.7 S	H	10004651	5	3.83	YES
2" CC	10" DIPS	Brass	4.7 S	H	10004645	5	4.15	YES
2" CC	12" IPS	Brass	4.7 S	H	10004664	5	4.00	YES
2" CC	12" DIPS	Brass	4.7 S	H	10004728	5	3.89	YES

(PE3408/PE4710) ELECTROFUSION TRANSITION SADDLE w/Brass Outlet & FPT Threads

Outlet Size	Main Size	Outlet Type	Pin Type	Clamp Type	Part Number	Pack. Qty.	Wt.	AWWA
¾" FPT	2" IPS	Brass	4.7 R	B	10004681	10	2.15	YES
¾" FPT	3" IPS	Brass	4.7 R	C	10004695	10	2.32	YES
¾" FPT	4" IPS/DIPS	Brass	4.7 R	D/L	10004711	5	2.41	YES
¾" FPT	6" IPS/DIPS	Brass	4.7 R	E/M	10004736	5	2.57	YES
¾" FPT	8" IPS	Brass	4.7 R	H	10007754	10	2.32	YES
¾" FPT	8" DIPS	Brass	4.7 S	H	call	-	-	-
¾" FPT	10" IPS	Brass	4.7 S	H	10004732	10	2.35	YES
¾" FPT	10" DIPS	Brass	4.7 S	H	call	-	-	-
¾" FPT	12" IPS	Brass	4.7 S	H	call	-	-	-
¾" FPT	12" DIPS	Brass	4.7 S	H	call	-	-	-
1" FPT	2" IPS	Brass	4.7 R	B	10004684	10	2.02	YES
1" FPT	3" IPS	Brass	4.7 R	C	10004698	10	2.32	YES
1" FPT	4" IPS/DIPS	Brass	4.7 R	D/L	10004715	5	2.28	YES
1" FPT	6" IPS/DIPS	Brass	4.7 R	E/M	10004739	5	2.46	YES
1" FPT	8" IPS	Brass	4.7 R	H	10007755	10	2.21	YES
1" FPT	8" DIPS	Brass	4.7 S	H	10004731	10	2.33	YES
1" FPT	10" IPS	Brass	4.7 S	H	10004649	10	2.35	YES
1" FPT	10" DIPS	Brass	4.7 S	H	10004641	10	2.38	YES
1" FPT	12" IPS	Brass	4.7 S	H	10004662	10	2.58	YES

Call for availability of other sizes and dimensions.

4.7R = 4.7 Pin with Resistor

4.7S = 4.7 Solid Pin