ADAPTER • FITTING continued COPPER PRESSURE WROT CONNECTION CAST FTG x M WC-404 C-104 NIBCO **ELKHART** WROT CAST WROT CAST 4704-2 604-2 704-2 104-2 Part Box Master Approx. Nominal Size Dimensions 3 Number Qty. Qty. Net.Wt. В С 2 - REDUCING - $1/2" \times 3/8"$ W 01432 750 1-7/32 A 01474* $3/4" \times 1"$.27 1-31/32 25 250 1-23/32 3/4" × 1/2" W 01447 25 250 .13 $1" \times 3/4"$ W 01464 25 250 .19 2-3/64

AIR CHAMBER		COPPER PRESSURE								
		WROT WA-515 WROT ELKHART		CONNECTION FTG				CAST		
				CAST N/A	WROT 619		NIBCO	CAST N/A		
	N	Nominal Size			t Box Master Approx.			Dimensions		;
	I	2	3	Number	Qty.		Net.Wt.	Α	В	C
r A	I 1/2" × 6"	2	3	Number W 06000	Qty.		Net.Wt.	A 6	В	C
A A B	1 1/2" × 6" 1/2" × 12		3			Qty.			B 	C

WROT

WC-106

BUSHING • FLUSH



NIBCO **ELKHART** WROT CAST WROT CAST 119 N/A 618 N/A Nominal Size Part Box Master Approx. Dimensions Qty. Qty. Net.Wt. С Number Α $1/4" \times 1/8"$ W 01706 3,400 10. 3/8 100 W 01712 $3/8" \times 1/4"$ 100 4,000 10. 7/16 $3/8" \times 1/8"$ W 01714 100 2,400 .02 7/16 $1/2" \times 3/8"$ W 01715 100 1,500 .02 9/16 $1/2" \times 1/4"$ W 01717 100 1,500 .04 9/16 5/8" × 1/2" W 01720 50 750 .03 11/16 5/8" × 3/8" W 01721 750 50 .06 11/16 W 01722 $5/8" \times 1/4"$ 50 750 .08 11/16 3/4" × 5/8" W 01725 50 500 .04 13/16 $3/4" \times 1/2"$ W 01726 50 500 .07 13/16 3/4" × 3/8" W 01727 50 500 .11 13/16 I" × 3/4" W 01737 500 .12 31/32 50 $1" \times 5/8"$ W 01738 500 .18 31/32 50 1" × 1/2" 31/32 W 01739 25 250 .22 |-|/4" × |" 1-1/32 W 01743 10 200 16 $1-1/4" \times 3/4"$ W 01745 10 200 .30 1-1/32 $1-1/2" \times 1-1/4"$ W 01750 100 .22 1-5/32 10 $1-1/2" \times 1"$ W 01751 10 100 .41 1-5/32 $2" \times 1 - 1/2"$ W 01758 1-13/32 10 100 .68 2" × I-1/4" W 01759 50 .94 1-13/32 $2-1/2" \times 2"$ W 01767 50 .92 1-17/32

CONNECTION

FTG x C

COPPER PRESSURE

CAST