





Wrot & Cast Drainage Fittings


Adapters, Upturns, & Traps

| | | | | |
|---|--|-----------------|----------------|---------------------|
| WROT | DWV-Trap Upturn Male to OD Fine Thread | | | CAST 5427 |
|  | | | | |
| M x O.D. Fine Thread | | | | |
| Nominal Size In Inches | Part Number | Box Quantity | Master Pack | Approx. Net Wt. |
| **1 1/2 x 1 1/2 OD | 50416 | - | 50 | 1.110 |

| | | | | |
|--|--|-----------------|----------------|---------------------|
| WROT | DWV-P-Trap with Cleanout Copper to Copper to Cleanout W/Plug | | | CAST 5551 |
|  | | | | |
| C x C x Cleanout W/Plug | | | | |
| Nominal Size In Inches | Part Number | Box Quantity | Master Pack | Approx. Net Wt. |
| ** 1 1/4 | 49770 | - | 50 | 1.210 |
| ** 1 1/2 | 49772 | 1 | 25 | 1.530 |
| ** 2 | 49776 | 1 | 12 | 2.260 |
| *** 3 | 49780 | - | 10 | 5.740 |

| | | | | |
|--|---------------------------------------|-----------------|----------------|---------------------|
| WROT | DWV-P-Trap Copper to Copper | | | CAST 5550 |
|  | | | | |
| C x C | | | | |
| Nominal Size In Inches | Part Number | Box Quantity | Master Pack | Approx. Net Wt. |
| **1 1/4 | 49750 | - | 50 | 1.090 |
| **1 1/2 | 49752 | 1 | 25 | 1.450 |
| **2 | 49758 | 1 | 12 | 2.110 |
| **3 | 49762 | - | 10 | 5.170 |

| | | | | |
|---|--|-----------------|----------------|---------------------|
| WROT | DWV-P-Trap with Cleanout Copper to SJ to Cleanout W/Plug | | | CAST 5555 |
|  | | | | |
| C x SJ x Cleanout W/Plug | | | | |
| Nominal Size In Inches | Part Number | Box Quantity | Master Pack | Approx. Net Wt. |
| **1 1/2 x 1 1/2 OD | 49842 | - | 50 | 1.800 |

| | | | | |
|--|--|-----------------|----------------|---------------------|
| WROT | DWV-P-Trap with Union Joint Female N.P.T. to SJ L.A. Pattern | | | CAST 5556 |
|  | | | | |
| F x SJ | | | | |
| Nominal Size In Inches | Part Number | Box Quantity | Master Pack | Approx. Net Wt. |
| **1 1/2 x 1 1/2 OD | 49952 | - | 25 | 2.090 |