## UNION **COPPER PRESSURE** CONNECTION WROT CAST $C \times F$ C-109\* **ELKHART** NIBCO WROT WROT CAST CAST 733-3 N/A 4733-3 Part Nominal Size Box Master Approx. Dimensions 3 Number Qty. Qty. Net.Wt. В С 2 3/8" A 11421\* 200 1-3/32 1/2" A 11422\* 25 125 .26 1-1/8 3/4" A 11423\* 150 .37 1-5/16 25 A 11424\* Ι" 1-7/16 100 .61 10 1-1/4" A 11425\* 50 .98 1-19/32 1-1/2" A 11426\* 1.21 1-13/16 50 2" A 11427\* 25 1.9 2-5/32

## COPPER TUBE STRAP • PERFORATED **COPPER PRESSURE** CONNECTION WROT CAST WS-1101 **ELKHART** NIBCO WROT CAST WROT CAST 623 N/A 125 N/A Nominal Size Part Box Master Approx. Dimensions 2 Number Qty. Net.Wt. Qty. 25 Ft. Roll A 01211\* 10 1.63 .75

## COPPER TUBE STRAP • TWO-HOLE **COPPER PRESSURE** WROT CONNECTION CAST WS-1100 C **ELKHART NIBCO** WROT WROT CAST CAST 120 N/A 624 N/A Nominal Size Part Box Master Approx. Dimensions 1 Number Qty. Net.Wt. 1/8" A 01203 4,000 100 ١٥. 1/4" 5,600 3,400 A 01278 3/8" A 01366 ١٥. 100 A 02529 1/2" 100 1,500 10. 5/8" A 01467 100 2,000 10. 3/4" A 02574 ١٥. <u>750</u> A 02614 50 750 .02 1-1/4 50 500 .04 A 02650 50 500 .05 1-1/2" A 02675 A 02708 500

## **HANGER • HI EAR COPPER PRESSURE** WROT CONNECTION CAST C W-125 **NIBCO ELKHART** WROT CAST WROT CAST 124 N/A Nominal Size Part Box Master Approx. Dimensions 2 3 Number Qty. Qty. Net.Wt. Α C A 03167\* 100 1,000 .03 1-5/8 47/64 3/4" 1-5/8 .04 A 03168\* 500 A 03171\* 250 .04 1-1/8

