


OLDAKER TEST LEADS & ACCESSORIES

Call 888.295.9516

Fax 888.295.9517

SCOPE PROBES



SCOPE PROBE SELECTION CHART

| PART # | ATTEN | B.W.MHz @ 30B | RISE | LOADING | | LENGTH | DC MAX |
|---------------|------------|------------------|--------------|---------|------|--------|-----------|
| | | | TIME N.S. | pF | MO | | |
| 3501 | SWT 1X-10X | 5/100 | 70/3.5 | 90/16 | 1/10 | 5 FOOT | 500 V |
| 3502 | SWT 1X-10X | 10/200 | 35/1.4 | 60/15 | 1/10 | 5 FOOT | 500 V |
| 3503 | FIXED 1X | 20 | 17.5 | 45 | 1 | 5 FOOT | 500 V |
| 3504 | FIXED 10X | 100 | 3.5 | 15 | 10 | 5 FOOT | 500 V |
| 3504RP | FIXED 10X | 100 | 3.5 | 15 | 10 | 5 FOOT | 500 V |

| | | | | | | | |
|---------------|------------|-------|--------|-----|----|--------|-------|
| 3505 | FIXED 10X | 200 | 1.4 | 13 | 10 | 5 FOOT | 500 V |
| 3505RP | FIXED 10X | 200 | 1.4 | 13 | 10 | 5 FOOT | 500 V |
| 3506 | FIXED 10X | 100 | 11.0 | 10 | 60 | 6 FOOT | 500 V |
| 3510 | FIXED 100X | 100 | 3.5 | 4 | 10 | 5 FOOT | 500 V |
| 3511 | FIXED 1X | 12 | 60 | N/A | | 6 FOOT | 500 V |
| 3512 | FIXED 1X | 15 | 23.3 | N/A | | 6 FOOT | 500 V |
| 3513 | FIXED 10X | 300 | 1.16 | N/A | | 5 FOOT | 500 V |
| 3514 | SWT 1X-10X | 6/100 | 58/3.5 | N/A | | 6 FOOT | 500 V |
| 3515 | SWT 1X-10X | 6/250 | 58/1.4 | N/A | | 6 FOOT | 500 V |