# **TEXTURE PRODUCTS (NON-AGGREGATED)** PROFORM<sup>®</sup> BRAND PERFECT SPRAY<sup>®</sup> EM PERFECT SPRAY<sup>®</sup> HF



#### **GENERAL INFORMATION**

## **GENERAL APPLICATION**

Perfect Spray EM and Perfect Spray HF are non-aggregated spray textures used to create a wide range of textures for wall and ceiling surfaces.

Perfect Spray EM is specially formulated for easy mixing and easy pumping.

Perfect Spray HF mixes and pumps easily and dries to a harder finish.

### **FEATURES/BENEFITS**

- Designed to work with standard spray equipment.
- Excellent pumpability.
- Wide array of patterns: spatter, spatter knockdown, and orange peel.
- Used for both walls and ceilings.

#### SPECIFICATIONS/MIXING

#### Sizes:

Perfect Spray EM Bag Size: 50'lb. (22.7 kg)

Coverage: 500-1,500 sq. ft./bag (46.5-139.2 m²/22.7 kg)

Perfect Spray HF

Bag Size: 40 lb. (22.7 kg)

Coverage: 400-1,200 sq. ft./bag (46.5-139.2 m<sup>2</sup>/22.7 kg)

Note: Coverage of Perfect Spray EM and Perfect Spray HF will vary with the type of equipment used and the type of texture desired.

#### SPRAY EQUIPMENT

- Low Pressure: Application can be accomplished by using Hopper-type hand guns with nozzle openings of 3/16" to 1/4" and adjusting operating pressures and consistency of mix to achieve desired texture effects.
- High Pressure: Application using a spray texture gun fed by a piston pump, a Mayno-type pump or a bottom outlet pressure pot. Spatter size can be changed by adjusting atomizing pressure and consistency of mix. Higher atomizing pressure and thinner mix will result in smaller spatter while lower atomizing pressure and heavier mix will give a larger spatter.
- Caution: Avoid creating dust. When mixing, ventilate area, wear eye protection and a NIOSH- or MSHA-approved respirator for dust. Keep out of reach of children.

Note: These are general instructions. Complete, easy-to-follow application guidelines are printed on all bags of Perfect Spray EM or Perfect Spray HF. Close adherence to instructions for surface preparation and priming will avoid the problems of color variation, bleeding or sagging, and will permit the texture to achieve its full potential.









Perfect Spray EM/HF -Spatter



Perfect Spray EM/HF -Spatter + Knockdown