



## CLAMP-ON ACCESSORIES

### 3000A Clamp-on Adapter



- Flexible clamp for easy “fishing” around a conductor.
- 3000A AC current measuring accessory.
- 24" long.
- Perfect for any multimeter that reads AC millivolts.
- Accessories included: (1) 9V battery.
- Lifetime Limited Warranty.

CAT. NO.	UPC NO.	DESCRIPTION
CMAF-3000	07533	3000A Clamp-on Adapter
CMAF-3000-C*	07608*	3000A Clamp-on Adapter

\* Includes Certificate of Calibration

#### SPECIFICATIONS

<b>Amperage Measurement</b>	300, 3000A
<b>Voltage Output</b>	300A – 10mV output per 1 amp input 3000A – 1mV output per 1 amp input
<b>Clamp Length</b>	24" (610 mm)
<b>Measurement Category</b>	CAT III, 1000V

### AC/DC Clamp-on Current Adapter



- AC/DC current measuring accessory.
- Measure up to 600 amps.
- Perfect for any multimeter that reads AC and DC millivolts.
- Accessories included: (1) 9V battery.
- Lifetime Limited Warranty.

CAT. NO.	UPC. NO.	DESCRIPTION
CMA-60	07531	AC/DC Clamp-on Current Adapter

#### SPECIFICATIONS

<b>Amperage Measurement</b>	0-600A
<b>Voltage Output</b>	100 amp range – 10mV output per 1 amp input 600 amp range – 1mV output per 1 amp input
<b>Jaw Opening</b>	1.38" (35 mm)
<b>Measurement Category</b>	CAT III, 300V; CAT II, 600V

### Clamp-on Current Adapter



- AC current measuring accessory.
- Measures up to 400A AC.
- Perfect for any multimeter that reads AC millivolts.
- Lifetime Limited Warranty.

CAT. NO.	UPC. NO.	DESCRIPTION
CMA-40	07530	Clamp-on Current Adapter

#### SPECIFICATIONS

<b>Amperage Measurement</b>	0.1-400A
<b>Voltage Output</b>	1mV per 1 amp input
<b>Jaw Opening</b>	1.18" (30 mm)
<b>Measurement Category</b>	CAT III, 300V; CAT II, 600V

### 93-30 Line Splitter (NEMA 5-15)



- For use with all models of clamp-on meters.
- Splits lines for independent testing with clamp-on meter.
- Lifetime Limited Warranty.

CAT. NO.	UPC. NO.	DESCRIPTION
93-30	34452	93-30 Line Splitter (NEMA 5-15)

#### SPECIFICATIONS

<b>Size</b>	4-5/8" x 1-3/4" (118 mm x 45 mm)
<b>Weight</b>	0.1 lb. (45g)