

Electrofusion Fittings: Transition Saddles (Corp Saddles)

Outlet Material: Brass 360 Alloy

Compression Ring Material: Stainless 304



(PE3408/PE4710) ELECTROFUSION TRANSITION SADDLE w/Brass Outlet & FPT Threads

Outlet Size	Main Size	Outlet Type	Pin Type	Clamp Type	Part Number	Pack. Qty.	Wt.	AWWA
1" FPT	12" DIPS	Brass	4.7 S	H	10004642	10	2.41	YES
1¼" FPT	2" IPS	Brass	4.7 R	B	10004687	10	1.75	YES
1¼" FPT	3" IPS	Brass	4.7 R	C	10004701	10	1.85	YES
1¼" FPT	4" IPS/DIPS	Brass	4.7 R	D/L	10004718	5	2.23	YES
1¼" FPT	6" IPS/DIPS	Brass	4.7 R	E/M	10004741	5	2.21	YES
1¼" FPT	8" IPS	Brass	4.7 R	H	10007756	5	2.26	YES
1¼" FPT	8" DIPS	Brass	4.7 S	H	call	-	-	YES
1¼" FPT	10" IPS	Brass	4.7 S	H	10004650	10	2.35	YES
1¼" FPT	10" DIPS	Brass	4.7 S	H	call	-	-	-
1¼" FPT	12" IPS	Brass	4.7 S	H	call	-	-	-
1¼" FPT	12" DIPS	Brass	4.7 S	H	call	-	-	-
1½" FPT	2" IPS	Brass	4.7 R	B	10004690	10	1.75	YES
1½" FPT	3" IPS	Brass	4.7 R	C	10004704	10	2.06	YES
1½" FPT	4" IPS/DIPS	Brass	4.7 R	D/L	10004721	5	2.16	YES
1½" FPT	6" IPS/DIPS	Brass	4.7 R	E/M	10004744	5	2.53	YES
1½" FPT	8" IPS	Brass	4.7 R	H	10007752	15	2.17	YES
1½" FPT	8" DIPS	Brass	4.7 S	H	10004733	10	2.23	YES
1½" FPT	10" IPS	Brass	4.7 S	H	call	-	-	-
1½" FPT	10" DIPS	Brass	4.7 S	H	10004652	10	2.59	YES
1½" FPT	12" IPS	Brass	4.7 S	H	call	-	-	-
1½" FPT	12" DIPS	Brass	4.7 S	H	call	-	-	-
2" FPT	2" IPS	Brass	4.7 R	B	10004678	10	3.45	YES
2" FPT	3" IPS	Brass	4.7 R	C	10004692	5	3.65	YES
2" FPT	4" IPS/DIPS	Brass	4.7 R	D/L	10004707	5	3.70	YES
2" FPT	6" IPS/DIPS	Brass	4.7 R	E/M	10004722	5	4.49	YES
2" FPT	8" IPS	Brass	4.7 R	H	10007763	5	4.05	YES
2" FPT	8" DIPS	Brass	4.7 S	H	10004656	5	4.27	YES
2" FPT	10" IPS	Brass	4.7 S	H	10004653	5	4.43	YES
2" FPT	10" DIPS	Brass	4.7 S	H	call	-	-	-
2" FPT	12" IPS	Brass	4.7 S	H	10004665	5	4.21	YES
2" FPT	12" DIPS	Brass	4.7 S	H	10004727	5	4.21	YES

Call for availability of other sizes and dimensions.

4.7R = 4.7 Pin with Resistor

4.7S = 4.7 Solid Pin