

HENRY®



320 Set&Grout™

Premixed Adhesive & Grout

Easily Set Quarry,
Stone, Ceramic &
Mosaic Tile

- Use for setting quarry, stone, ceramic & mosaic tile
- Premixed for fast and easy installation
- Great for bathrooms, showers and backsplashes
- Good sag resistance

THE PROFESSIONAL'S FORMULA FOR SUCCESS™

HENRY®

320 Set&Grout™

HENRY® 320 Set&Grout™ Premixed Adhesive & Grout is a ready-to-use adhesive and grout specially formulated for the installation of quarry, ceramic, and mosaic tile on walls. HENRY 320 Set&Grout can be used to install or repair tile in showers, in bathrooms, and on backsplashes.

USE FOR:

Installing quarry, ceramic and mosaic tile (10"x10" or smaller)*

* In areas where a water-resistant grout material is needed, use HENRY Flex Grout for grouting.

BONDS TO: Concrete, concrete block, cement backer boards, drywall, wood substrates, and existing ceramic tile.

SURFACE PREPARATION:

Substrate must be sound, smooth, dry, clean, and free of excessive moisture or alkali. Remove dirt, wax, loose paint, and all other foreign matter that would interfere with a good bond, such as curing agents or sealers.

INSTALLATION AS AN ADHESIVE:

- Stir any liquid on the surface into the adhesive.
- Full spread adhesive evenly with flat side of recommended trowel to obtain a good mechanical bond. Do not leave bare spots. Then comb adhesive with the notched side of trowel.
- Install tile immediately. Working time on concrete is up to 30 minutes. Working time on all other substrates is 40 to 50 minutes. Do not allow adhesive to skin over.
- Push the tile into the adhesive with adequate pressure to ensure that the tiles are fully adhered. Check to make sure adequate transfer is being achieved.
- Allow adhesive to dry 24 hours on walls and 48 hours on floors before grouting.
- Remove excess adhesive immediately using a damp cloth.

INSTALLATION AS GROUT:

- Stir any liquid on the surface into the adhesive.
- Make sure adhesive or setting material has been allowed to dry adequately before grouting.
- Working in small areas, use a squeegee or rubber grout float to push Set&Grout into the grout joints. Wipe any excess material from the face of the tiles with a damp sponge or cloth before it has dried.
- Allow grout a minimum of 24 hours to dry. When grout has dried, polish the entire grouted surface with a clean, dry cloth.

COVERAGE:

1-Gallon Unit

- Up to 40 sq. ft. per gallon when used as adhesive.

1-Quart Unit

- Up to 10 sq. ft. per quart when used as adhesive.

Color: white

Available in quarts and gallons

CLEAN UP:

Note: Do not reuse container. Dispose of container and adhesive residue in accordance with federal, state, and local waste disposal regulations.

Do not flush adhesive down drains.

- Store between 41°F (5°C) and 90°F (32°C). Protect from freezing.
- Shelf life is one year if unopened.
- VOC content: 60g/L; calculated & reported, SCAQMD 1168.

WARRANTY:

For complete warranty details, contact your dealer or our Customer Service Center at 800-232-4832.

HENRY®

The W.W. Henry Company
400 ARDEX Park Drive
Aliquippa, PA 15001
(724) 203-8000

Customer Service and Technical Information
1-800-232-4832
www.wwhenry.com

HS149 (11/07)

HENRY Commitment

HENRY is committed to helping you get the best results in professionally installed floors. 70 years of experience combined with our relationships with the leading resilient, wood and carpet manufacturers ensure that you receive the products and the support you need to complete the job successfully and profitably.

THE PROFESSIONAL'S FORMULA FOR SUCCESS™